



# Service Bulletin

**Date:** November 3, 2014

**Product Line:** Snowmobile

**Bulletin No:** BS201506

**Subject:** ECM Reprogramming

**Affected Models:** All 2014 ZR/XF 7000 and specific 2015 ZR/XF 7000 models

■ **NOTE:** Refer to **Cat Tracker Online** to obtain the list of affected VIN's from your inventory by selecting the "Service" tab, then the "Bulletin Display" tab. Specific criteria is required to be selected. Example: Bulletin Type-All, Product Type-SNOW, Bulletin Number BS201506 and Bulletin Year 2015.

---

**Condition:** The ECM mapping does not meet Arctic Cat standards and should be updated.

**Solution:** Reprogram the ECM according to the instructions included with the CATT II Tool. Once the ECM has been reprogrammed, log onto Cat Tracker Online, select the bulletin BS201506, and file the warranty claim.

**Warranty:** A labor allowance of 0.2 hr will be paid per affected snowmobile.

■ **NOTE:** It is required to enter the current mileage of each affected model.

 <b>ATTENTION</b>
--

To ensure that the necessary service work is completed in a timely manner and that this issue can be resolved, Arctic Cat is requesting that all service work be completed prior to November 3, 2015. All warranty claims directly related to this issue will not be honored after November 3, 2015, without prior approval.
--